

Building Inspection Report

Inspection Details

Date / Time of Inspection:

Type of Report:

Pre-Purchase Building Inspection

Address of Property:

Client Details

Client Name:

Client Email Address:

Client Phone:

Real Estate Agent Octails

Agent Name:

Company:

Mobile:

Email Address:

Ir spector Details

Inspector Name

Inspector Office:

Inspector Phone:

Inspector Email Address:

iSPECT

Building Inspection Report

iSPECT Building Inspections offers property inspection services for your poperty, by highly qualified inspection experts. Each of the inspectors agrees to comply with and are performance managed against iSPECT's Code of conduct. For further information about your report call 1300 477 328 or for further information on our code of conduct please visit https://ispect.com.au/code-of-conduct



TABLE OF CONTENTS


| 1. Description of property | 4 |
|---|----|
| 2. Definitions | |
| 3. Inspection Agreement | 7 |
| 4. Terms & Conditions | 9 |
| 5. Hallways and general living spaces | 11 |
| 6. Kitchen | 17 |
| 7. Laundry | 20 |
| 8. Bedrooms | 22 |
| 8.1. Bedroom 1 | 22 |
| 8.2. Bedroom 2 | 25 |
| 8.3. Bedroom 3 | 28 |
| 8.4. Bedroom 4 | 30 |
| 9. Bathrooms | 33 |
| 9.1. Bathroom 1 | 33 |
| 9.2. Bathroom 2 | 36 |
| 10. Ensuite | 40 |
| 10.1. Ensuite 1 | 40 |
| 11. External of property > Exterior | 44 |
| 12. External of property > Roof aleas | 56 |
| 13. External of property > Sub Noor areas | 60 |
| 14. Findings and summary | 61 |
| 15. iSPECT Building respections | 62 |

1. Description of property

Brief description of the building and other structures on the property:

| Type: | Domestic | Duplex |
|------------|--------------|--------|
| Bedrooms: | 4 | |
| Bathrooms: | 2 | |
| Ensuites: | 1 | |
| Car Park: | Single | |
| Height: | Two Story | |
| Building: | Brick Veneer | |
| Piers: | Concrete | |
| Floor: | Slab | |
| Roof: | Metal | |
| Age: | New build | |







| Weather at | t time of inspection? |
|--------------|--|
| Fine | |
| Was the pr | roperty furnished at time of inspection? |
| No | |
| Please note: | To conduct an inspection in accordance with AS 4349.1 the property would be vacant of all furnishing to enable a thorough visual inspection. |
| Was there | evidence of any extensions at time of inspection? |
| No | |
| Comment: | |
| Services co | onnected to property |
| Electricity: | Yes |
| Comment: | |
| Gas: | Yes |
| Comment: | |
| Water: | Yes |
| Comment: | |
| Sewer: | Yes |
| Comment: | |
| Drainage: | Yes |
| Comment: | |
| Smoke Detec | Yes Not tested |
| Comment: | |



| 2. Definitions | |
|----------------------------------|---|
| Definition of terms used t | to describe the current state of repair for each item inspected |
| Condition Visually Fine: | When the Inspector has viewed the subject area and sees no major defect, and sees no safety hazard. |
| General Advice/Minor Defect | A general impression regarding the extent of minor defects. Minor defects are common to most properties and may include minor blemishes, corrosion, cracking, weathering, general deterioration, unevenness, and physical damage to materials and finishes, such as desilvering of mirrors. It is expected that defects of this type would be rectified as part of normal ongoing property maintenance. |
| Major Defect | A defect of sufficient magnitude where repair works must be carried out, in order to avoid unsafe conditions, loss of utility or further deterioration of the property. Repairs should be carried out by a suitably qualified or licenced trades person. A Major Defect where insafe conditions are immediately present and which must be repaired at the earliest opportunity. |
| Unable to Inspect Due to access: | An area of the site where there is insufficient, unsafe or unreasonable access. |
| Not Applicable (N/A): | When the subject field doesn't make up any part of the inspected property. |
| Report Definition | |
| Shower Recesses: | Tests may be made on shower recesses to detect leads (towater is connected). The tests may not reveal leaks or show incorrect waterproofing if silving liquid or masonry sealant has been applied prior to the inspection. Such application is temporary waterproofing measure and may last for some months before preaking down. The tests of shower recesses are limited to running water within the recesses and visually checking for leaks. As shower are only checked for a short period of time, prolonged use may reveal leaks were not detected at the time of inspection. No condende of a current leak during inspection does not necessarily mean that the shower does not leak |
| Glass Caution: | Glazing in some building (builds fore 1978), may not necessarily comply with current glass safety standards AS1288. In the interests of safety, glass panes in doors and windows especially in high traffic areas should be replaced with safety glass of have shatterproof film installed. |
| Stairs & Balustrades: | The Australian Building Code 3.9 require that covering stairs, landings and balustrades ensure the safety of all occupants and visitors to a building. Those built prior to 1996 may not comply with the current standard. You must upgrade all such items. |
| Swimming Pools: | A prol is subject to a special purpose property report and is not applicable to this report. |
| Rooms Below Ground Level | Rooms under the house or below ground level (whether they be habitable or not) may be subject to dampness and water penetration. Drains are not always installed correctly to these areas or could be blocked. It is common to have damp problems and water entry into these spaces, especially during periods of heavy rainfall and may not be evident on the day of the visual inspection. These rooms may also not have council approval. The purchaser hould make their own enquiries to Council to ascertain if approval was granted. |
| Owners Corporation | If the property is covered by an Owners Corporation (Strata Title) iSPECT recommend that an Owners Corporation search be conducted to ascertain their financial position, the level of maintenance afforded and any other relevant information that may impact your future ownership of the property. |



3. Inspection Agreement

Requirement for inspection agreement

AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building are which is in reasonable condition, having been adequately maintained over the life of the building. This means that building inspected may not comply with Australian Standards, building regulations or specific state or territory requirements app the time of the inspection.

Purpose of inspection

The purpose of the inspection is to provide advice regarding the condition of the property at the time of the in

Reasonable Access to the property at time of inspection?

Note: Yes

is not available are excluded from and do not doors, security system, pets, furniture or Areas where reasonable entry is denied to the inspector or where reasonable form part of the inspection. Access limitations may include legal right of ked dog other obstructions. Physical access limitations may include height bound rance, thick vegetation, small roof or crawl space and adverse weather conditions. The report shall ig within the scope of the inspection that rtify an area or it

was not inspected and the factor that prevented inspection.
The extent of accessible areas shall be determined by the inspec inspection based on the conditions areas and areas that are within the inspector's line of sight encountered at that time. The inspection shall include only access and close enough to enable reasonable appraisal.

Reasonable access includes a prerequisite that the rimum clearance. pecified in the table below are safely available. Dimensions for reasonable access:

- 600mm crawl space; and accessible from a 3.6m ladder; Roof Interior: 400mm x 500mm access hole
- Roof exterior: 400mm x 500mm access hole; 6 crawl space; and accessible from a 3.6m ladder placed on the ground

Supplementary notes:

- · Reasonable access does not include cutting of ccess holes or the removal of screws and bolts or any other fastenings or sealants to access covers.
- · Sub-floor areas sprayed be inspected unless it is safe to do so. th cher cals à

Conditions

An inspection report n al on: ond

- itions or recent occupancy and use of services that mightaffect observations. The client or agents of the client. Prevailing ther co ditio
- ed b Informati
- Deliberate c f defects.
- other relev factor limiting the inspection.

Scop of ispection

t reported on, general exclusions detailed in AS 4349.1 – 2007

- or building that are under construction;
- nspection is not intended to include rigorous assessment of all building elements in a property;
- ects that would only be apparent under particular weather conditions or when using particular fittings & fixtures;
- efects not apparent due to occupancy or occupancy behaviour e.g. non-use of a leaking shower; • The inspection report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing with the building in the future;
- Unauthorized building work or of work not compliant with building regulations;
- Title and ownership matters, matters concerning easements, covenants, restrictions, zoning certificates and all other lawrelated matters:
- Estimation of the cost of rectification of specific defects.

What is not reported on, specific exclusions detailed in AS 4349.1 - 2007

· Footings below ground, concealed damp-proof course, electrical installations, operation of smoke detectors, light switches and fittings, TV, sound and communication and security systems, concealed plumbing, adequacy of roof drainage as installed,



gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming pools and associated filtration and similar equipment;

• The operation of fireplaces and solid fuel heaters, including chimneys and flues, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, ducted vacuum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, lead content, radon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators);

· Soil conditions, control joints, sustainable development provisions, concealed framing-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furniture and accessories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, energy efficiency, lighting efficiency.

What is reported on

The inspection includes subjective appraisal by an inspector competent to assess the condition of residential buildings. It involves a subjective assessment so different inspectors or even the same inspector on a different occasion may reach different conclusions.

The inspection comprises a visual assessment of the property to identify major defects and to form an opinion re general condition of the property at the time of inspection. The following areas shall be inspected where applic

- The interior of the building: ceilings; walls; floors; windows; doors & frames; kitchen; bathroom; WC; ensuite damp problems;
- The exterior of the building: walls (including lintels, claddings, doors & windows); timber or steel chimneys; stairs; balconies, verandas, patios, decks, suspended concrete floors, balustrades;
 The roof exterior: roof (including tiles, shingles & slates, roof sheeting, gables, flashings); skylight
- s, vents, flu alley guttering; downpipes; eaves, fascia's and barges;
 - The roof space: roof covering; roof framing; sarking; party walls; insulation;
- floors;
- The sub-floor space: timber floor (including supports, floor, ventilation, drainage, dan
 The property within 30m of the house and within the boundaries of the site: car accompany moda n, det laundry, ablution facilities and garden sheds; retaining walls (where supporting other structures and la paths & driveways; steps; fencing (general & swimming pool); surface water (drainage taining walls > 700mm high); caping



4. Terms & Conditions

iSPECT Terms & Conditions

General

- 1. iSPECT Building Inspections (iSPECT) has prepared this report in accordance with the guidelines of **Australian Standard 4349.1 2007 Inspection of buildings Part 1: Pre-purchase inspections Residential Buildings** (the Standard) which covers the minimum requirements for the visual inspection of residential buildings and based on the inspection of the property by the Inspector named in the building inspection report.
- 2. The Report is prepared for the sole and exclusive use of the Client (person, persons or body) named in the Booking Confirmation and cannot be used or acted upon by any other party without the express permission of iSPECT.
- 3. The Terms and Conditions are available on the website: www.iSPECT.com.au and can change without notice.
- 4. The Client, having been provided with the opportunity to read these Terms and Conditions following the miking of a boking and a payment for an inspection, accepts these Terms and Conditions.
- 5. The Client acknowledges that these Terms and Conditions take precedence over any oral or written apprecentations made by iSPECT or the Inspector, to the extent of any inconsistency.
- 6. A report prepared in accordance with the Standard is not a certificate of compliance of the property within the equirements of any Act, regulation, ordinance, local law or by-law, or as a warranty or an insurance policy against problems developing with the building in the future.

The Inspection

- 7. All inspections will be a **non-invasive visual** inspection and will be limited to those area and sections of the property to which Reasonable Access (see below) is both available and permitted on the date application.
- 8. The inspection is undertaken, and the Report prepared, by the Inspector on the Lordington that the existing use of the Inspected Property will continue. As such, the Inspector will not assess the fitness of the Inspected Property for any other intended purpose. We advise you to verify any proposed change in use of the Inspected Property with the relevant authorities.
- 9. Where the Inspected Property is a unit or apartment (Strata 7 te), inspected areas will be limited to the nominated residence and does not include common property. i.e. Only those items lead on the title shall be reported.
- 10. The Inspected Property shall be compared with a building that was constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

Reasonable Access

- 11. The Standard provides that "safe and reasonable access" shall be determined by the inspector at the time of the inspection, based on the conditions encountered at the time of his pection. An inspector shall only inspect areas where safe, unobstructed access is provided and where the minimum clearances are vailable or, where these clearances are not available, areas within the inspector's unobstructed line of sight and close enough to enable reasonable appraisal.
- 12. Minimum clearances are defined at least 600 mm vertical and horizontal clearance for roof space and sub floor area access. The interior and exterior roof must be accessible om a 3.6 metre high ladder for reasonable access to be available.
- 13. Reasonable access toes in sing de removing screws and bolts to access covers. Nor does reasonable access include cutting or making access trails a moving surniture or stored goods.

Limitations

- 14. **No assessment or identification** is made of asbestos or asbestos related products, toxic mould, Methamphetamine or other harmful substances. As pecus dust is a hazardous material and should not be disturbed. It is vital that asbestos is not sawn, sanded, drilled or water blasted, etc. For more information about the handling and disposing of asbestos contact your local country.
- 15. Our inspection lives not assess the operation of appliances, alarms, security and communication systems, smoke detectors, heating and cooling systems, blinds (internal and external), soft furnishings, telephones, spa and pool equipment, building automation, electrically operated doors, plant and equipment. Any item not specifically noted in this Report is excluded from the inspection of the Inspected Property. We suggest that a licensed tradesperson be contacted for a separate report in respect of gas releastical appliance and fittings.
- 16. No tem of furniture or fixtures will be removed, moved or modified during the inspection and items and conditions covered by such furnishings and fixtures are not inspected or considered. Nor do we assess the condition of conspicuous, non-structural items such as carpets, vinyl floor coverings etc.
- 17. The Inspector can only make comment about the general, visible condition of electrical wiring and plumbing. We suggest that a licensed tradesperson be contacted for a separate report.

The Inspection Report

18. The Report must be read carefully and, in its entirety, to gain a complete understanding of the findings of the inspection of the Inspected Property. It will help you understand the limitations faced by an inspector and why it is not possible to guarantee that a property is completely free of defects.




- 19. This Report describes the visual assessment of the Inspected Property including: the relevant features of the Inspected Property within 30m of the building and within the boundaries of the site, the prevailing structural, soil and weather conditions at the date and time of the inspection.
- 20. The Report is a subjective assessment of the Inspected Property and therefore outlines the opinion of the Inspector on the general condition of the Inspected Property at the date and time of the inspection in relation to major defects or safety hazards and a general advice on minor defect items.
- 21. The Report does not cover any part of the building located beneath the ground surface or identify any unauthorised building work or of work not compliant with building regulations.
- 22. An estimate of the costs of rectification of defects is not required in accordance with the Standard.
- 23. Any maintenance and general advice items are intended as a helpful guide. The Report is not an exhaustive list of all maintenance and advice items.
- 24. The Report provides no guarantee and is not a warranty against problems developing with the Inspected Property in he future.
- 25. This Report is not a rigorous assessment of all building elements and does not cover all maintenance items. This Report as does not cover defects in inaccessible areas, defects that are not reasonably visible, defects that may only be apparent in certain weather conditions or defects that have not yet arisen due to prolonged periods of wet or dry weather cubes when events.
- 26. The Building or Pre-purchase Inspection Report does not identify the presence of timber pests, or any damage caused by timber pests (e.g. termites, borers, etc.). If you wish to include this, you will need to request a Timber Pest inspect on report. If there is a concern regarding other types of pests then a fully qualified Pest Controller should be contained.


Other matters

- 27. You should address legal and conveyancing matters such as title and owners up to you solicitor or legal representative. Compliance issues in relation to the positioning of services, privacy, vehicle access, the siting of the buildings, zoning, permit or town planning issues or other legal matters should be directed to the relevant authority or to a plicitor or legal representative.
- 28. Unless otherwise notified, iSPECT Building Inspections will make vendor purposed reports available to prospective buyers. Please advise within 48 hours of receipt of this report if, as a vendor word on not wish this report to be made available to prospective purchasers of the property.



5. Hallways and general living spaces





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due to Access | Not Applicable |
|------------|----------------------------|-----------------------------------|--------------|------------------------------------|----------------|
| Floor | ₫ | | П | | |
| Walls | | ₫ | | | |
| Ceilings | | Ø | | | |
| Doors | | Ø | | | |
| Windows | ₫ | | | | |
| Fireplace | | | | | ₫ |
| Stairs | | | | | |
| Balustrade | ₫ | | | | |

Hallways and general living spaces **General Advice/Minor Defect** Walls Comments Wall imperfections and cracking to timber work joints.







Hallways and general living spaces

General Advice/Minor Defect

Doors

Comments

Scratches and imperfections to staining.








Hallways and general living spaces **General Advice/Minor Defect** Stairs Comments Wall imperfections and cracking to timber work joints to stair and under stair area.







6. Kitchen





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due to Access | Not Applicable |
|--|----------------------------|-----------------------------------|--------------|------------------------------------|----------------|
| Floor | ₫ | | | | |
| Walls | | Ø | | | |
| Ceilings | | ₫ | | | |
| Doors | | ₫ • | | | |
| Windows | ₫ | | | | |
| Cabinets / Drawers | ₫ | | | | |
| Benchtops | ₫ | | | | |
| Sink/Taps | ₫ _ | | | | |
| Appliances (Oven, Range Hood, Dishwasher) | ø | | | | |
| Ventilation | | | | | ₫ |

Kitchen


General Advice/Minor Defect

Doors

Comments

Barn door guide allignment isssue not closing and stay sealed of finishing flush.





Kitchen

General Advice/Minor Defect

Walls

Comments

Wall imperfections and cracking to timber work joints.







Kitchen **General Advice/Minor Defect** Ceilings Comments Ceiling imperfections including joint cracking to cornice.



7. Laundry





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due to Access | Not Applicable |
|--------------|----------------------------|-----------------------------------|--------------|------------------------------------|----------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | | |
| Ceilings | ₫ | | | | |
| Doors | ₫ | | | | |
| Windows | | | | | ₫ |
| Trough/Sink | ₫ | | | | |
| Taps | ₫ | | | | |
| Cabinets | ₫ _ | | | | |
| Sealants | Ø | P | | | |
| Exhaust Fans | Ø | | | | |
| Ventilation | | | | | ₫ |

Laundry

General Advice/Minor Defect

Walls

Comments

Wall imperfections and cracking to timber work joints.

Significant gap between architrave of the door to the wall.









8. Bedrooms

8.1. Bedroom 1





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | (nable to inspect Due Access | Not Applicable |
|-----------------|----------------------------|-----------------------------------|--------------|------------------------------|----------------|
| Floor | | | | | |
| Walls | | ₫ | | | |
| Ceilings | | I | | | |
| Doors | ₫ | | | | |
| Windows | ₫ | | | | |
| Robes | | | | | |
| Smoke Detectors | | | | | ₫ |


Bedroom 1

Major Defect

Floor

Comments

Significant deviations to Noor and Noor squeak present.







Bedroom 1 **General Advice/Minor Defect** Walls Comments Wall imperfections and cracking to timber work. Bedroom 1 **General Advice/Minor Defect** Comments Downlight broken.

Bedroom 1

General Advice/Minor Defect

Robes

Comments

Wall cnd ceiling imperfections and cracking to timber work.











8.2. Bedroom 2





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to his vect Due | ot Applicable |
|-----------------|----------------------------|-----------------------------------|--------------|------------------------|---------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | | |
| Ceilings | ₫ | | | | |
| Doors | | Ø | | | |
| Windows | ₫ | | | | |
| Robes | ₫ | | | | |
| Smoke Detectors | | | | | ₫ |

Bedroom 2 **General Advice/Minor Defect** Walls Comments Wall imperfections and cracking to timber work.



Bedroom 2
General Advice/Minor Defect

Comments

Rough door edge finish.



8.3. Bedroom 3





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to I, spect Due | Not Applicable |
|-----------------|----------------------------|-----------------------------------|--------------|------------------------|----------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | P | |
| Ceilings | ₫ | | | | |
| Doors | ₫ | | | | |
| Windows | ₫ | | | | |
| Robes | ₫ | | | | |
| Smoke Detectors | | | | | ₫ |

Bedroom 3


General Advice/Minor Defect

Walls

Comments

Wall imperfections and cracking to timber work.

Gaps around robe frame.















8.4. Bedroom 4

| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to laspect Due | Not Applicable |
|-----------------|----------------------------|-----------------------------------|--------------|-----------------------|----------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | | |
| Ceilings | | ₫ | | | |
| Doors | ₫ | | | | |
| Windows | ₫ | | | | |
| Robes | ₫ | | | | |
| Smoke Detectors | | | | | Ø |

Bedroom 4 **General Advice/Minor Defect** Walls Comments Wall imperfections and cracking to timber work.



Bedroom 4 Ceilings **General Advice/Minor Defect** Comments Cornice joint cracking.



9. Bathrooms

9.1. Bathroom 1





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Vinable to Inspect Due | Not Applicable |
|---------------|----------------------------|-----------------------------------|--------------|------------------------|----------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | | |
| Ceilings | I | | | | |
| Doors | đ | | | | |
| Windows | ₫ | | | | ₫ |
| Shower Recess | ₫ | | | | |
| Shower Screen | ₫ | | | | |
| Shower Rose | Ø | P | | | |
| Bath | | | | | ₫ |
| Mixer Taps | Ø | | | | |
| Cabinets | | | | | |
| Sealanto | | Ø | | | |
| Basins | ď | | | | |
| Toilet | | ₫ | | | |
| Ventikation | ₫ | | | | |

Bathroom 1


General Advice/Minor Defect

Walls

Comments

Grout discolouration within shower recess area.





Bathroom 1

General Advice/Minor Defect

Sealant

Comments

Poor sealant finish and gaps and discolouration present.





Bathroom 1

General Advice/Minor Defect

Toilet

Comments

Toilet seat loose and not connected.





9.2. Bathroom 2





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due | ot Applicable |
|---------------|----------------------------|-----------------------------------|--------------|-----------------------|---------------|
| Floor | ₫ | | | | |
| Walls | | ₫ | | P | |
| Ceilings | | ₫ | | | |
| Doors | | Ø | | | |
| Windows | ₫ | | | | |
| Shower Recess | ₫ | | | | |
| Shower Screen | ₫ | | | | |
| Shower Rose | ₫ | | | | |
| Bath | | | | | ₫ |
| Mixer Taps | Ø | | | | |
| Cabinets | < Ø | | | | |
| Sealants | V | | | | |
| Basins | | | | | |
| Toilet | ď | | | | |
| Ventilation | Ø | | | | |



Bathroom 2

General Advice/Minor Defect

Walls

Comments

Wall imperfections and cracking to timber work joints.







Bathroom 2 **General Advice/Minor Defect** Ceilings Comments Imperfections and setting issues to ceiling square set cornice.



Bathroom 2 **General Advice/Minor Defect** Doors Comments Door edge rough sawn.

10. Ensuite

10.1. Ensuite 1





| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due | Not Applicable |
|---------------|----------------------------|-----------------------------------|--------------|-----------------------|----------------|
| Floor | ₫ | | | Ō | |
| Walls | | Ø | | | |
| Ceilings | | Ø | | | |
| Doors | | Ø | | | |
| Windows | ₫ | | | | |
| Shower Recess | | | d | | |
| Shower Screen | ₫ 🛕 | | | | |
| Shower Rose | ✓ | | | | |
| Bath | | | | | ₫ |
| Taps | | Ø | | | |
| Cabinets | Ø | | | | |
| Sealants | Ø | | | | |
| Basins | ď | | | | |
| Toilet | đ | | | | |
| Ventilation | ₫ | | | | |

Ensuite 1

Major Defect Shower Recess

Comments

Shower recess non compliant, water pooling issues present, allowed time for water to run off to floor waste and water was still present.





General Advice/Minor Defect

Taps

Comments

Tap loose.





Ensuite 1

General Advice/Minor Defect

Walls

Comments

Delamination of mirror.





Ensuite 1

General Advice/Minor Defect

egin, V

Comments

Ceiling imperfections and damag present.





Ensuite 1

General Advice/Minor Defect

Doors

Comments

Door edge flaking and rough sawn.

Hole to the door edge.







| 11. External of property > Exterior | | | | | |
|-------------------------------------|----------------------------|-----------------------------------|--------------|------------------------------------|----------------|
| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due to Access | Not Applicable |
| Walls | | ₫ | | | |
| Windows | ď | | | | |
| Doors | ₫ | | | | |
| Fascia, Eaves, Bargeboards | | ₫ | | | |
| Down Pipes | | ₫ | | | |
| Deck, Verandah, Balcony, Patio | | ₫ | | | |
| Steps | | | | Ф | M |
| Handrails | | | | | ₫ |
| Pergola | | | | | Ø |
| Driveways and Paths | | ₫ | | | |
| Retaining Walls | đ | | | | |
| Garage/Car Port | | ₫ | | | |



General Advice/Minor Defect

Deck, Verandah, Balcony, Patio

Comments

Chipped floor tile in multiple locstions to both front porch and alfresco.

Rear alfresco brickwork presenting none compliant brick joints, brickwork not straight and stepping including missing mortar and cracking to mortar.


Alfresco ceiling running out of level.


As per wall comments refer to this area.























General Advice/Minor Defect

Walls

Comments

Efflorescence, manganese and algae staining and build up to walls in multiple locations.

Gaps and cracking present to mortar joints throughout.

Significant brick allignment issues including brick stepping issues throughout the house with thicker than acceptable brick joints with the most significant area presenting rear alfresco.

Gaps to cladding to balcony area.

Front projection cladding area to the front right side loose and not sitting flush with gaps present.

Gaps to service penetrations.

Hot water cover missing.

Damaged brick upper left hand side.

Weephole obstructions present due to mortar breaches.

Alfresco weep holes covered due to floor finish higher than base of the weep hole with risk of water-ingress.






























General Advice/Minor Defect

Fascia, Eaves, Bargeboards

Comments

Eaves out of level.

Under coat and prep work issues to eaves.












General Advice/Minor Defect

Down Pipes

Comments

Scratches to downpipes throughout.





External > Exterior

General Advice/Minor Defect

Driveways and Paths

Comments

Garage rebate lower than the driveway and driveway sitting higher, creating a water pooling issue.







General Advice/Minor Defect

Garage/Car Port


Comments


Rectify paint imperfections to walls, including rectification of prep work and gap filling to adjoining walls and timber work.

Garage presenting a significant cracking the boundary of presenting structural concerns, it is recommended this item refered to an engineer for assessment, scope of works and cost of repairs.



















Major Defect

Site Drainage

Comments

Site drainage appears minimat for new build with council main present through the site, front pit concealed with turf presenting a silt risk entering waterways, serious non compliance in this area.







12. External of property > Roof areas

Roof Type: Low-pitched / flat roof



| | Condition Visually | General | | Unable to Inspect Due | |
|------------|--------------------|------------------------|--------------|-----------------------|----------------|
| | Fine | Advice/Minor Defect | Major Defect | 10 Access | Not Applicable |
| Roof Space | | | | ✓ | |
| Roof | | | | ✓ | |
| Valleys | | | | ď | |
| Flashings | | Ø | | | |
| Gutters | ₫ | | | | |
| Pointing | | | | | ₫ |
| Skylights | | | | | ₫ |
| Vents | | | | | ₫ |
| Chimney | | | | | ₫ |

External > Roof Areas


Unable to Inspect Due to Access

Roof Space

Comments

Flat pitch roof and unaccessible due to located over stair void area.





External > Roof Areas

Unable to Inspect Due to Access

Roof

Comments

Roof exceeds 3.6m access point, rear lower roof from where it can be assessed appears to oit sit straight based on roof line.





External > Roof Areas

Unable to Inspect Due to Access

Valleys

Comments

Valleys on upper roof can't be accessed.





External > Roof Areas


General Advice/Minor Defect

Flashings

Comments

Gaps present in flashings, causing between barge and flashing water leaks and ingress causing algae and manganese reaction.













| 13. External of property > Sub floor areas | | | | | | |
|--|----------------------------|-----------------------------------|--------------|------------------------------------|----------------|--|
| | Condition Visually Fine | General Advice/Minor Defect | Major Defect | Unable to Inspect Due to Access | Not Applicable | |
| Sub Floor Ventilation | | | | | Ø | |
| Stumps | | | | | ď | |
| Framing | | | | | | |
| | | | | | | |



14. Findings and summary

This Building Inspection summary provides you with a "snapshot" of the items the inspector considers of greatest significance for you, in respect of the building only, when considering this property. Please refer to the Definitions and the complete Report for detailed information regarding visible defects. Note that this Summary is not the complete Report and that in the event of an apparent discrepancy the complete Report overrides the Summary information.

Report Summary

Items stated within the report, however this is a building inspection for pre purchase purposes, as per the houses age it is a new build, there are many significant concerns with non compliance with this such as brick work, drainage and the likes that are of concern in which do not comply with the 2017 guide to tolerance and standards, this house is built post 2017 being a new build.

Major Defects noted

Yes

A summary of any major defects found. A defect of sufficient magnitude where recording on has to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or serious injury; loss of utility, whereby the defect is such that the whole of the relevant part of the building can no longer serve its intended function; or further substantial deterioration of the building.

As noted within the report.

Major Structural Defect Noted

No

A major defect in any internal or external primary load bearing component of the building which seriously affects the structural integrity of the building requiring rectification to be carried out without undue delay to avoid: unsafe conditions, posing a threat to life or serious injury; loss of atility, hereby the effect is such that the whole of the relevant part of the building can no longer serve its intended function of further substantial deterioration of the building. In the case of cracking, a serious structural defect denotes severe cracking as refined at Category 4, Appendix C – Australian Standard AS 2870-2011.



15. iSPECT Building Inspections

The iSPECT Building Inspections is a national franchise building inspections business. iSPECT engages with trade qualified builders with a minimum of 10 years residential and commercial building experience to complete property inspections. Each home and building inspection completed is then detailed in a report that is completed to Australian Standards AS4349.0, AS4349.1 and/or AS4349.3. iSPECT has franchise nationally who are supported by a national call centre located at 8 Applerson Street, Port Melbourne. Our office locations follow:



